

Nº 9562

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 12-14-83

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 1317

SIZE OF PIPE USED

6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

102 WEST OF MH 9' DEEP

WAS LATERAL AT CURB?


YES

WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

SCHAEER

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

William Hammer

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Call D.D. By Bill Lewis

Nº 9562

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, Dec. 14

RECEIVED OF Robert Schaefer & Son FEE OF \$ 25

FOR WHICH PERMISSION IS GRANTED Don Brunker

TO TAP Sanitary SEWER ON THE South

OF Cherry Rd N.W. AVE. ST. TYPE OF STREET Black Top

THE PREMISES BEING LOT NO. O.W. 99, HOUSE NO. 1317

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Schaefer

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**