FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED / 2 - 15 - 7 3	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 1343	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 166 EAST 0 FM 8'D
WAS LATERAL AT CURB? YES	
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	
	344
	N 5253
SIGNED William Hammer	2.3.72 107.
Inspector for City	FILED AT ENGINEER'S OFFICE
REMARKS	

Nº 9565

OFFICE OF THE DIRECTOR OF PUBLIC SEF PERMIT TO TAP SEWER

	MASSILLON, OHIO, Duc. 19
RECEIVED OF Schau Excar	N. FEE OF \$ 25
FOR WHICH PERMISSION IS GRANTED & Sic S	clumacher
TO THE Sametary SE	WER ON THE South
of Plant And W. AVE.	VPF OF STREET Plackty
THE PREMISES BEING LOT NO. 014.89	HOUSE NO. 13 43
· ·	O. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.	
NAME OF CONTRACTOR Schair	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.