

✓✓
N^o 9577

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 2-24-84

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 914

SIZE OF PIPE USED 6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT 35' North of MH 7' DEER
CURB LINE AND DEPTH


WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN

NAME OF CONTRACTOR SCHAEER

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

N



SIGNED William Hammer
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 9577

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, FEB. 23

RECEIVED OF L & P MILLER FEE OF \$ 2.00

= N.W.

FOR WHICH PERMISSION IS GRANTED L & P MILLER

TO TAP SANITARY SEWER ON THE EAST

OF PRINCE HORN CIRCLE NW AVE. TYPE OF STREET ASPHALT

THE PREMISES BEING LOT NO. 11788, HOUSE NO. 914

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

CAV.

NAME OF CONTRACTOR SCHAEER EXCAV

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.