Nº 9582

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 3-19-84	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT 43' North of M. 6'DEBR CURB LINE AND DEPTH
WAS LATERAL AT CURB?	NAME OF CONTRACTOR HOLE BELLEN
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR # 6 4 5 13 13 4 4 4
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL	L OF BUILDING SERVED.
	71D 801 45°B
SIGNED William Lannin Inspector for City	FILED AT ENGINEER'S OFFICE
REMARKS	<u> </u>

Nº 9582

## OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	PROTO: MASSILLON, OHIO, 3 /3/84
COPRBAUM	PROTOS MASSILLON, OHIO, JOS FEE OF \$
UT AVE SUU.	FOR WHICH PERMISSION IS GRANTED THE THE THE THE PROTOS
	TO TAP ANTARY SEWER ON THE SOUTH
	OF TREMONT ST. TYPE OF STREET ASPH
	THE PREMISES BEING LOT NO. 14125 , HOUSE NO. 29-TREMONT,
417.1918 S,10.	WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.
105 CONS.	NAME OF CONTRACTOR AND PROTES COMME
- <i>1</i>	Note: This permit covers work outside of building only. Any work

walls of building is subject to Massillon Board of Health Regulations.