Nº 9592

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL	OF BUILDING SERVED.
, 	
	•
SIGNED NO INSPECTIO	N FILED AT ENGINEER'S OFFICE
Inspector for City	
DENTANA	
KEMAKAS	

COT № 9592

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

MASSILLON, OHIO, APPIL 26
RECEIVED OF MASSILIDAL COMMUNITY HOSDITAL FEE OF \$ 5
FOR WHICH PERMISSION IS GRANTED BEAKER EXCAUATING
CONDIT OF SANT SEWER ON THE SANITARY SOVI
OF STATE STATE ST. TYPE OF STREET HACO SUKE
THE PREMISES BEING LOT NO. 2054, HOUSE NO. 644
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR BEAVER EXCAV

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.