№ 9597 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 5- 4-84	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 906	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT 38 North of M4 9'D CURB LINE AND DEPTH
WAS LATERAL AT CURB?	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	L OF BUILDING SERVED.
	13. 3.D
<u>-</u>	- = 38/ ≫
SIGNED William Hammun Inspector for City	FILED AT ENGINEER'S OFFICE
REMARKS	**************************************

№ 9597

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OF	110. May 4	
RECEIVED OF Thereater Fine 12			FEE OF \$
for which permission is granted $\mathcal{H}ANEF$.	& LIND	A RODOCKE	ER LOLD L
го тар		and the second	
OF PRINTERS AVE. ST. TO	PE OF STREET	<u> </u>	<u> Ial</u>
THE PREMISES BEING LOT NO. 1/1787			
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE N			
NAME OF CONTRACTOR AUGUST SCHAFA	E SOM'S	<u>EXCA</u> UATIAIG	CO.

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.