Nº 9626

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED \$572060, 12, 1989	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 409	
SIZE OF PIPE USED CVT-OFF	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH
WAS LATERAL AT CURB?	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR 6/CN TISSOT
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.	
	T
	← 75' → M4
	2 / 2 Time 15
a/a	L7 Deep
SIGNED Harell Source Inspector for City	FILED AT ENGINEER'S OFFICE
REMARKS Placed With C'em	ent. Sewer one Frot OFF LOT live East Corn

CUT-CFF

## OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

MASSILLON.	оню, Стар 17
RECEIVED OF Callast Luckeya	FEE OF \$
FOR WHICH PERMISSION IS GRANTED Than I Than	
Cortor Santage Sewer on the	The Down
OF AVE. ST. TYPE OF STREET	. Chye had
THE PREMISES BEING LOT NO. 4148	,
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 OF THE DEPARTMENT OF PUBLIC SERVICE.	
NAME OF CONTRACTOR Latitutt	f 

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.

1914