ü 9637

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED Scott. 24 1984	IF SO HOW AND LOCATION FROM LUye 62FT
HOUSE NO. 629	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT 62FT 8FT Deep CURB LINE AND DEPTH 62FT 8FT Deep
WAS LATERAL AT CURB? JES	
WAS ATTACHED TO MAIN_VES	NAME OF CONTRACTOR Holder DAUM
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL	OF BUILDING SERVED. 1610 From House S, W. CORNER N-
	3-30° Ponch
	45° - 125T
	150
	No. of the second secon
αI	- A
	<i>.</i>
SIGNED LATTORE SOSANO)	FILED AT ENGINEER'S OFFICE
Inspector for City	
REMARKS	

Nº 9637

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

•		- /		11
	MASSILLON,	OHIO,	<u> </u>	
RECEIVED OF Jun Public	21	<u> </u>	/ 	FEE OF \$ 25
	Desta	7	•	
FOR WHICH PERMISSION IS GRANTED				
TO TAP	SEWER ON THE		11157	·
OF		<u>, 184</u>	8 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	<u> </u>
THE PREMISES BEING LOT NO. 11115	· · · · · · · · · · · · · · · · · · ·	, HOUSE NO	629	·
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE OF THE DEPARTMENT OF PUBLIC SERVICE.		DULY PASSEC	BY THE CIT	Y COUNCIL, AND
NAME OF CONTRACTOR Antidudent	n/			

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.