№ 964

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM			
NOUSE NO	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH			
WAS LATERAL AT CURB?	D100			
WAS ATTACHED TO MAINSHOW BY DIAGRAM RELATION OF LATERAL TO WALL				
	7) A 23'			
	17716			
SIGNED NO TUSPECTOR	FILED AT ENGINEER'S OFFICE			
REMARKS				

Nº 9646

OFFICE OF THE DIRECTOR OF PUBLIC SEF PERMIT TO TAP SEWER

		MASSILLON,	оню,	of 17
RECEIVED OF	Can To dra			FEE OF \$
FOR WHICH PERMISSION IS GRAN				<i>u</i>
HEPA! JASA TO J			4	the state of the s
or	*.			
THE PREMISES BEING LOT NO				
WORK TO BE DONE IN ACCORDAN	CE WITH ORDINANCE		<i>P</i>	
OF THE DEPARTMENT OF PUBLIC	SERVICE.			
NAME OF CONTRACTOR	<u> </u>			

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.