

✓✓
Nº 9659

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 1-4-85 *by per Betty from H.S.* IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____
HOUSE NO. 2746 _____
SIZE OF PIPE USED _____ DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____
WAS LATERAL AT CURB? _____
WAS ATTACHED TO MAIN _____ NAME OF CONTRACTOR Holderbaum
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

SIGNED

Frank S. Searcy
Inspector for City

FILED AT ENGINEER'S OFFICE _____

REMARKS

No Tap

Nº 9659

OFFICE OF THE DIRECTOR OF PUBLIC SEWERS
PERMIT TO TAP SEWER

MASSILLON, OHIO,

JAN. 3,

RECEIVED OF

HOLDERBAUM

FEE OF \$

2

FOR WHICH PERMISSION IS GRANTED

GEO. PROTO S

TO TAP

SEWITARY

SEWER ON THE

NORTH

OF

LINCOLN W. WEST

AVE.

ST. TYPE OF STREET

ASPH & BRICK

THE PREMISES BEING LOT NO.

21.178

, HOUSE NO.

2746

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

HOLDERBAUM

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.

3/16/64