## Nº 9660 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED JANUARY 10 1985	IF SO HOW AND LOCATION FROM WE /72 FT
HOUSE NO877	/
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? 1/25	,
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR Holder baum
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	L OF BUILDING SERVED.
	7FT From Conner 1 - 20FT OUT
in the second of	H-CURB
SIGNED Harold Jasaron	FILED AT ENGINEER'S OFFICE
Inspector for City	State of the Control
BENDER REPAIR OF AFLATERAL III	wden Side Walk with 6" Clay pine 18" Dees (SAg'S)

EPHIC

## $N^{0}$ 9660

## OFFICE OF THE DIRECTOR OF PUBLIC SEF PERMIT TO TAP SEWER

RECEIVED OF Alexander	au l	lever		FEE OF \$Z	<u>ئ</u> ر ،
FOR WHICH PERMISSION IS GRANTED	Borway				
TO TAP 1 Secretary	sewer on th	IE	7/4/05		
OF 16 4- NOTECE NE	AVE. _ST. TYPE OF STR	EET <del>/</del>	Clarket	<u> </u>	
THE PREMISES BEING LOT NO52					
WORK TO BE DONE IN ACCORDANCE WITH ORDIN OF THE DEPARTMENT OF PUBLIC SERVICE.				COUNCIL, A	<b>1</b> D

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.