№ 9669

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED ARIL 17,1985	IF SO HOW AND LOCATION FROM GOES INTO MANHOLE IN HARD
HOUSE NO. 1900	FIRST MANHOLE DOWN STREAM SEES TO THE TOTAL SEES
SIZE OF PIPE USED 6" PIRSTIC	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH Goes into Manhole in year 54 FT Deep CURB LINE AND DEPTH.
WAS LATERAL AT CURB?	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR A.J. DIANIOSONE
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	·
31/FT Decrard Person Windo	ONT. IRON Wip 4F Deep AND Clear-out 18th 130F5 180F5 180F5 180F5
SIGNED HAROLL SOME PROPERTY OF CITY REMARKS	FILED AT ENGINEER'S OFFICE
17-11101111A ==============================	

Church Nº 9669

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

1 Mount

	MASSILLON, OH	110,1_4_4_4_4	
RECEIVED OF AT	Biana So	<u>ko</u> ,,,,,	FEE OF \$_25
FOR WHICH PERMISSION IS GRANTED	AT SHIELD	···	
то тар	SEWER ON THE	matt.	
OF UNICO NE		and the second s	
THE PREMISES BEING LOT NO	1.347 , H	OUSE NO	<u> </u>
WORK TO BE DONE IN ACCORDANCE WITH		LY PASSED BY THE CIT	r COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE	E. An	(

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.