

N^o 9674

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED April 16, 1985

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM W/E AT 155 FT

HOUSE NO. 1271 & 1277

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH 155 FT 8 FT Deep


SIZE OF PIPE USED 6

WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN Yes

NAME OF CONTRACTOR SCHAEER & SON

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Paul Lacey
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Send one Sewer Bill To 1271 Cherry Rd N.W. And The Other Bill To
Cherry Rd N.W. IF PROPERTY IS SPLIT-UP INTO TWO LOTS A NEW LATERAL MUST BE

2 Houses
2 separate houses

Top
N^o 9674

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, 11/22/70

RECEIVED OF

FEE OF \$

FOR WHICH PERMISSION IS GRANTED

TO TAP

SEWER ON THE

OF

AVE.

ST. TYPE OF STREET

THE PREMISES BEING LOT NO.

HOUSE NO.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.