Nº 967€

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 874	
SIZE OF DIPE LISED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	
	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL	OF BUILDING SERVED.
4	
- 1 - 1 - 1	
SIGNED 1 Iller Inspector for City	FILED AT ENGINEER'S OFFICE
Inspector for City	1 0
REMARKS Cutoff, 95 from	n center of road
	V

Cutoff

Nº 9676

OFFICE OF THE DIRECTOR OF PUBLIC SEF PERMIT TO TAP SEWER

	ma
2/85	MASSILLON, OHIO, May Z
Putnam	RECEIVED OF MARC COLUCY FEE OF \$ 5
hemout 3E	FOR WHICH PERMISSION IS GRANTED (ALUCY & MA)
ophalt	TO TAP 10/11/1 TAIL SEWER ON THE SE
5,8.	OF LONG SE AVE. ST. TYPE OF STREET CONDICAL +
J.C.	THE PREMISES BEING LOT NO. 9510 , HOUSE NO. 876
876	WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.
lucy Low	NAME OF CONTRACTOR CALUCY 4 Sons
TOO !	
/	Note: This permit covers work outside of building only. Any work
DUIG	walls of building is subject to Massillon Board of Health Regulations.