

Nº

9696

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED

9-20-85

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO.

1810

SIZE OF PIPE USED

6"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB?

YES

WAS ATTACHED TO MAIN

YES

NAME OF CONTRACTOR

Plus

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



125' 3/4' 6' DEEP AT HOUSE

241' 7"

7' 1/2" DEEP AT CURB

N4

SIGNED

William Pappas

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Repair
THRU
N^o 9696

OFFICE OF THE DIRECTOR OF PUBLIC SEWERS
PERMIT TO TAP SEWER

MASSILLON, OHIO, *Shp 2C*

RECEIVED OF *Plas. Inc.*

FEE OF \$ *2*

FOR WHICH PERMISSION IS GRANTED *same*

TO TAP *Sanitary*

SEWER ON THE *North*

OF *NE*

AVE.

ST. TYPE OF STREET *uphill*

THE PREMISES BEING LOT NO. *3059*

HOUSE NO. *1810*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *Plas. Inc.*

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**