## № 1 9699 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 10-9-85	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 1316	
SIZE OF PIPE USED CUT-OFF	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
 WAS LATERAL AT CURB?	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR COTTRE!
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL	L OF BUILDING SERVED.
	L OF BUILDING SERVED.  Manual
Janes Hall Sasan	FILED AT ENGINEER'S OFFICE
Inspector for City	
REMARKS ONE DRAW Comer Clos.	e d

(1177// № 9699

## OFFICE OF THE DIRECTOR OF PUBLIC SEF PERMIT TO TAP SEWER

	MASSILLON, OHIO,			
RECEIVED OF	FEE OF \$			
FOR WHICH PERMISSION IS GRANTED	Cottale this bear			
TO TAPSE				
OF/ \( \frac{\( \text{\Cor} \) \( \Co	PE OF STREET AND ALACE			
THE PREMISES BEING LOT NO.				
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND				
NAME OF CONTRACTOR	in kingelleteckerke			
NAME OF CONTRACTORS				

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.