## Nº 9701 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

HOUSE NO. 430 323 OSA	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM  DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?NO	·
WAS ATTACHED TO MAIN_ 4E.5	NAME OF CONTRACTOR 16 alseleum
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	L OF BUILDING SERVED.
ENGLY WSO	N4
SIGNED Willein Passage Inspector for City	FILED AT ENGINEER'S OFFICE
DEMARKS	
REMARKS	

OFFIC	E OF THE DIRECTOR OF PUBLIC SE
Nº 9701	PERMIT TO TAP SEWER
Cores & Julies, Sh	1101 2010

Cores & Tubes In 323 Poalula Sw.		
RECEIVED OF TWENTY -E	IVE DOLLARS OF FEE OF \$ 1	
FOR WHICH PERMISSION IS GRANTED HOLDERBAUM		
TO TAP SANITARY	SEWER ON THEEAST	
OF CLEVELAND S.W.	ST. TYPE OF STREET CHIP & SEAL 1100	
THE PREMISES BEING LOT NO. 4181	42/2 HOUSE NO. 1200 323	
WORK TO BE DONE IN ACCORDANCE WITH ORDIN	ANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND	

OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR HOLDER BAUM

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.