Nº 9702 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 12.5.83	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED 6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? 4 5 5 WAS ATTACHED TO MAIN 4 5 5	NAME OF CONTRACTOR Plas Ever
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	L OF BUILDING SERVED.
52/1/20 = 1/5%	
307 -71	
SIGNED William Page Inspector for City	FILED AT ENGINEER'S OFFICE

Nº 9702

OFFICE OF THE DIRECTOR OF PUBLIC SEF PERMIT TO TAP SEWER

I/m 1	フヤ
MASSILLON, OHIO, 100.	<u> </u>
RECEIVED OF Sweats Live 00	FEE OF \$25
Was Encer.	•
FOR WHICH PERMISSION IS GRANTED	
TO TAP SANUTAU SEWER ON THE CAST	
	1
OF 159 St. M.W. AVE. ST. TYPE OF STREET Chip &	Seal
and the	
THE PREMISES BEING LOT NO. 1938 , House No. 386	_
THE PREMISES BEING LOT NO, HOUSE NO, HOUSE NO	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CIT	Y COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC-SERVICE.	
Ma Comer	e Na
NAME OF CONTRACTOR - F 100 - F	
	w.
	_

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.