

Nº 9717

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 4-15-86

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 523

SIZE OF PIPE USED CUT-OFF


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR CATRILL CONST

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

Paul J. Searcy
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

CONCRETE FLOOR DRAINS

N^o 9717

Post off
OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, *April 14th*

RECEIVED OF *Five Dollars*

FEE OF \$ *5*

FOR WHICH PERMISSION IS GRANTED *Castell Construction*

TO TAP *Sanitary*

SEWER ON THE *West*

OF *4th St*

AVE.

ST. TYPE OF STREET *Chippewa & Canal*

THE PREMISES BEING LOT NO. *747*

HOUSE NO. *523*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *Castell Construction*

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**

4TH ST. N.E