Nº 9730

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 8-29-86	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM 203
HOUSE NO. 2322	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? 15	
WAS ATTACHED TO MAIN 455 SHOW BY DIAGRAM RELATION OF LATERAL TO WA	NAME OF CONTRACTOR
-	
r—7	N 4
	l e de la companya d
8'086 2031	DOWN STREM MI,
SIGNED William Payson Inspector for Cit	FILED AT ENGINEER'S OFFICE
C A A A A A A A A	,

CUTOFI

Nº 9730

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

	MASSILLON, OHIO,	4/13
RECEIVED OF 1015/00	bracac	, FEE OF \$\sum_2
FOR WHICH PERMISSION IS GRANTED COCO		
Out the second to the second	WER ON THE	11)
OF (1)(())() AVE. ST. TY	PE OF STREET.	WASLACT
	7 , HOUSE NO	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO		
OF THE DEPARTMENT OF PUBLIC SERVICE.	J. N.	
NAME OF CONTRACTOR	1/10	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.