Nº 9749 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

HOUSE NO. 224 SIZE OF PIPE USED 4"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?_465	
WAS ATTACHED TO MAIN 765	NAME OF CONTRACTOR Holderbeaum
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.	
mi (11) 1 2'2" DEEN	19' FROM SWCORNER OTHORSE 2'DEEP
SIGNED Willia Papas Inspector for City	FILED AT ENGINEER'S OFFICE
REMARKS	

Repair Carbon Copyl

Nº 9749

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

MARKED AND KITT 24
MASSILLON, OHIO,
RECEIVED OF TOTAL SEE OF \$2
RECEIVED OF THE PROPERTY OF TH
The same of the sa
FOR WHICH PERMISSION IS GRANTED X V / D
HOTAP Santary SEWER ON THE
THE SEVEN ON THE CONTROL OF THE SEVEN ON
OF Tuves II AVE. ST. TYPE OF STREET AND SOAL
The state of the s
THE PREMISES BEING LOT NO. 1369 House No. 224
THE PREMISES BEING LOT NO. / DE / HOUSE NO HOUSE NO
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.
It Chaluman

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.