Nº 9751

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. 6/2	DISTANCE FROM FIRST MANHOLE	
SIZE OF PIPE USED	DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB? YES		
WAS ATTACHED TO MAIN YES	NAME OF CONTRACTOR	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
	L'ouif	
SIGNED William Canada Inspector for City	FILED AT ENGINEER'S OFFICE	
REMARKSCutoffp	·	

n toff

9751

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

0	MASSILLON, OHIO, // //	
RECEIVED OF	Councy	FEE OF \$
FOR WHICH PERMISSION IS GRANTED	COLUCY	·
TO TAP SALM	sewer on the	AST
OF 612 YOUNG SI	AVE.	
THE PREMISES BEING LOT NO	9431, HOUSE NO.	612
WORK TO BE DONE IN ACCORDANCE W	/ITH ORDINANCE NO. 19.1971 DULY PASSI /ICE.	ED BY THE CITY COUNCIL, AND
NAME OF CONTRACTOR	COLUCY	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.