

N^o 9757

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 1-20-87

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 392'

HOUSE NO. 893

SIZE OF PIPE USED 4"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? Yes

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR Holdenbaum

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

William Rogers

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Repair

Repair

Nº

9757

Office, Jan. 22
OFFICE OF THE DIRECTOR OF PUBLIC SEE
PERMIT TO TAP SEWER

MASSILLON, OHIO, JAN 16

RECEIVED OF CARL HOLDEFELBAUM FEE OF \$ 25

FOR WHICH PERMISSION IS GRANTED CATTILANDS

TO TAP SAN. SEWER ON THE SOUTH

OF WALNUT RD S.E. AVE. ST. TYPE OF STREET ASPH/CK

THE PREMISES BEING LOT NO. 10049, HOUSE NO. 893

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR HOLDEFELBAUM

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.