Nº 9762

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 3.19.87	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 2/8-220	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? 365	I
WAS ATTACHED TO MAIN 755	NAME OF CONTRACTOR B+B Wrickey
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	L OF BUILDING SERVED.
THE THE CURBILLY CURBILLY	N
CURDITY	ve
SIGNED Willin Page Inspector for City	FILED AT ENGINEER'S OFFICE
REMARKS	

Nº 9762

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

	MASSILLON, OHIO,	Alle.	18.,
RECEIVED OF	brecki	16	FEE OF \$
FOR WHICH PERMISSION IS GRANTED.	7 <u>~</u>		
то тар (142) sev	VER ON THE	<u>) 7012</u>	<u> </u>
OFAVE: ST. TY	PE OF STREET		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,
THE PREMISES BEING LOT NO	, House	: NO. 218	<u>-220</u>
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO OF THE DEPARTMENT OF PUBLIC SERVICE.). 19.1971 DULY F	ASSED BY THE CI	TY COUNCIL, AND
NAME OF CONTRACTOR			

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.