

Nº 9771

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 3-10-87

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 918

SIZE OF PIPE USED 4"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR Jim P. Las

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED William Pappas

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS Repair

Repair
Nº 9771

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, *May 10*

RECEIVED OF *Jim Plan*

FEE OF \$ *21*

FOR WHICH PERMISSION IS GRANTED *11/10*

TO TAP *Sanitary*

SEWER ON THE *W*

OF *Green*

AVE.

ST. TYPE OF STREET *C + S*

THE PREMISES BEING LOT NO. *3155*

HOUSE NO. *918*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *Jim Plan Excavating*

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**