

Nº


9774

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNEDDATE INSPECTED 4-13-87IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM135'HOUSE NO. 1242 RearSIZE OF PIPE USED —DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTHWAS LATERAL AT CURB? —WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR

Benson Const.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

William Pappas
135' 0 MM
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Cut-off near with house in front.

Cuttoff
N^o 9774

OFFICE OF THE DIRECTOR OF PUBLIC SER
PERMIT TO TAP SEWER

MASSILLON, OHIO, *April 27*

RECEIVED OF *Branche Etc*

FEE OF \$ *5*

FOR WHICH PERMISSION IS GRANTED *Same*

TO TAP *Cuttoff*

SEWER ON THE *W*

OF *Lincoln E*

AVE.

ST. TYPE OF STREET *Lincoln Ave*

THE PREMISES BEING LOT NO. *4544*

HOUSE NO. *1242 R*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *Branche Etc*

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**