

N<sup>o</sup>


9777

J  
FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNEDDATE INSPECTED 4-14-87IF SO HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM117'6"HOUSE NO. 1260SIZE OF PIPE USED -DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTHWAS LATERAL AT CURB? -WAS ATTACHED TO ~~MANHOLE~~Trunk Line

NAME OF CONTRACTOR

Besser Const.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

William Pappas

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Line Two END TREES up 84' from CURB 7' DEEP, Clear out over hill.

*Cutoff*  
N<sup>o</sup> 9777

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE  
PERMIT TO TAP SEWER

MASSILLON, OHIO, *May 27*

RECEIVED OF *W. B. Brown & Co.*

FEE OF \$ *5*

FOR WHICH PERMISSION IS GRANTED *Same*

TO TAP *Cutoff*

SEWER ON THE *R*

OF *Twentieth East*

AVE.

ST. TYPE OF STREET *Lawrence*

THE PREMISES BEING LOT NO. *9546*

HOUSE NO. *1260*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND  
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *W. B. Brown & Co.*

**Note:** This permit covers work outside of building only. Any work  
walls of building is subject to Massillon Board of Health Regulations.