Nº 9783 FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 4-28-87 HOUSE NO. 121	IF SO HOW AND LOCATION FROM 7 FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED 6 /1	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? YES	NAME OF CONTRACTOR Birelad Homes
SHOW BY DIAGRAM RELATION OF LATERAL TO WAI	LL OF BUILDING SERVED.
16 BACK From Cu	ESV.CuRB.
16 BACK From Cu	RB
SIGNED William Pappas	FILED AT ENGINEER'S OFFICE
/ jiispector for City	

T//

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

	MASSILLON, OHIO.	1,00.28	
RECEIVED OF RECEIVED OF	+101100	FEE OF \$	
FOR WHICH PERMISSION IS GRANTED	chic		
TO TAP VIA 110 (CC) SEN	NER ON THE	·	
OF	PE OF STREET		
THE PREMISES BEING LOT NO. 11/37	, HOUSE NO	121	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND OF THE DEPARTMENT OF PUBLIC SERVICE.			
NAME OF CONTRACTOR	1011(C)		

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.