

Nº 9796

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 7-9-87

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

166'

HOUSE NO. 516 Hamilton

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

-


SIZE OF PIPE USED 6"

WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN No

NAME OF CONTRACTOR Holderbaum

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED

William P. [Signature]

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Hooked onto next house lateral to the east.

N^o 9796

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO

July 2, 1987

RECEIVED OF

JIM HANMEL

FEE OF \$ 2

FOR WHICH PERMISSION IS GRANTED

JIM HANMEL

TO TAP

SANITARY
HAMILTON AVE
~~SANITARY~~

SEWER ON THE

NORTH

OF

AVE.

ST. TYPE OF STREET

CHIP SEAL

THE PREMISES BEING LOT NO.

13908

HOUSE NO.

516

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19,1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

HOLDERBAUM

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.