**№** 9797

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 7-10-87	If so how and location from $\mathcal{Q}\mathcal{Q}'$ first manhole down stream $\mathcal{Q}\mathcal{Q}'$	<del></del>
HOUSE NO. 15/1	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT	4.15
WAS LATERAL AT CURB? YES	CURB LINE AND DEPTH	
WAS ATTACHED TO MAIN_YES	NAME OF CONTRACTOR BOY & Claim	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL	L OF BUILDING SERVED.  N  R  R  R  R  R  R  R  R  R  R  R  R	West of the second seco
SIGNED William Popular Inspector for City	FILED AT ENGINEER'S OFFICE	
REMARKS House gos out los	er to 17 st.	

√10 № 9797

## OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

MASSILLON, OHIO,	1
RECEIVED OF FEE OF \$	2′
FOR WHICH PERMISSION IS GRANTED.	
TO TAP	
of (1) 1 1. (1) AVE.  ST. TYPE OF STREET.	
THE PREMISES BEING LOT NO. 7920/2/, HOUSE NO. 15//	<b></b>
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL,	AND
OF THE DEPARTMENT OF PUBLIC SERVICE.	
NAME OF CONTRACTOR	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.