√ 9800

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE THE ESTABLISHED TO SERVICE THE PROPERTY OF THE PROPERTY O	FIRST MANHOLE BEAM STREAM	
HOUSE NO. 1135	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB?	NAME OF CONTRACTOR	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
WAS ATTACHED TO MAINNAME OF CONTRACTOR		
	FILED AT ENGINEER'S OFFICE	
REMARKS		

Nº 9800

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

No. 18 Sept.	The SNOW BUT FOR
and the second second	MASSILLON, OHIO,
RECEIVED OF	HO-11/11/11/1 FEE OF \$ 2'
N.	and the second of the second o
FOR WHICH PERMISSION IS GRANTED	1 (1/6 De C) Arres Com
TO TAP	SEWER ON THE
**	
OF 2011	AVE,ST. TYPE OF STREET
THE PREMISES BEING LOT NO.	7475 , HOUSE NO. 1/35
	DRDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.	
NAME OF CONTRACTOR	dace r
A CONTRACT OF THE CONTRACT OF	7 - 4 Tolkini

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.