

Nº 9803

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 8-20-87

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 19

SIZE OF PIPE USED —

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

81 FT 4' Deep


WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR

Direct

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Harold Sams

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

OFFICE OF THE DIRECTOR OF PUBLIC SERVICES

PERMIT TO TAP SEWER

MASSILLON, OHIO.

RECEIVED OF

FEE OF \$5.00

FOR WHICH PERMISSION IS GRANTED

TO TAP.

TO TAP.

TO TAP.

TO TAP.

SEWER ON THE

SEWER ON THE

OF

AVE.

ST. TYPE OF STREET

ST. TYPE OF STREET

THE PREMISES BEING LOT NO.

HOUSE NO.

HOUSE NO.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

NAME OF CONTRACTOR

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.