

N^o 9813

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 12-21-87

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 4' Goes into MT in back yard

HOUSE NO. 1333

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? No

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR Malavitz

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED William Pappas

Inspector for City

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº

9813

TAP

OFFICE OF THE DIRECTOR OF PUBLIC SEW PERMIT TO TAP SEWER

MASSILLON, OHIO,

Apr 15

RECEIVED OF

Mularite Inc.

FEE OF \$ 2.00

FOR WHICH PERMISSION IS GRANTED

Same

TO TAP

Sanitary

SEWER ON THE

North

OF

Pinecrest Ave. N.E.

ST. TYPE OF STREET

THE PREMISES BEING LOT NO.

8764(8763)8824

HOUSE NO.

1333

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Mularite

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**