Nº ∫ 9819 ˈ

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 10-14-87	IF SO HOW AND LOCATION FROM 233'
HOUSE NO. 2561	DISTANCE FROM FIRST MANHOLE
SIZE OF PIPE USED6 ''	DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? 148 5	
	NAME OF CONTRACTOR Diance & Son.
SHOW BY DIAGRAM RELATION OF LATERAL TO WA	
9/0660 4.8 23/8640	N. A.
SIGNED William Panas Inspector for City	FILED AT ENGINEER'S OFFICE
REMARKS	

LARRY SUZCZEPANICK

Nº 9819

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

MASSILLON, OHIO
e O. T. D.
RECEIVED OF XMM COMPANY FEE OF SOL
FOR WHICH BERMISSION IS GRANTED XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX
FOR WHICH PERMISSION IS GRANTED 1
TO TAP Same to My SEWER ON THE SOUTH
OF DESIGNATION AND ST. TYPE OF STREET CAPACITY
751049 0511
THE PREMISES BEING LOT NO, HOUSE NO,
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19.1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.