Nº 09861

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 8-8-88	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED 6"	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? YES	NAME OF CONTRACTOR Ma
	ec ott bandb
ar h	
10'DEEP	Jan. be
SIGNED Bill Canally inspector for City	,

Nº 09861

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

MASSILLON, OHIO, JUNE 70, 1988
RECEIVED OF Malarytte FEE OF \$ 25.00
OR WHICH PERMISSION IS GRANTED
MULRILY PALL SEWER ON THE CARL SIDE SIDE
te premises being lot no. 1456/L House no. 1000
ORK TO BE DONE IN ACCORDANCE WITH SECTION 29 OF THE CODIFIED ORDINANCES OF THE CITY OF MASSILLON.
O. OF UNITS OWNER CALL CALLS AME OF CONTRACTOR MALASITE

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.