Nº 09862

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED JUNE 23 1988	IF SO HOW AND LOCATION FROM 5 FAST		
HOUSE NO. 2216			
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH		
WAS LATERAL AT CURB? Ye 5	,		
WAS ATTACHED TO MAINYES	NAME OF CONTRACTOR MALEVITE		
50	22/		
SIGNED Inspector for City			

イみ*プ* 09862

 N_0

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

		M	ASSILLON, OHIO,	VM KL	<u>23 , 19</u>
RECEIVED OF	Villas	<u>n) Ida</u>	vite.	<i>(</i> } 	FEE OF \$ 25.00
FOR WHICH PERMISSION	IS GRANTED	<u> </u>	11-6		
TO TAP	itan	SEWE	R ON THE	///	SIDE
of <u> </u>	2000	// AVE.	OF STREET		
THE PREMISES BEING L	от но/	4198	HOUSE	No. 22	16
WORK TO BE DONE IN A	CCORDANGE WITI	1	Y 1 1 1		1
NO. OF UNITS/_	OWNE	A 11/11/1	CAFIMO	MUNC X	MICHIU
NAME OF CONTRACTOR	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		<u> </u>		1.

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.