


N^o 10106

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 8-22-91IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM tapped 120' Downstream manholeHOUSE NO. 1723SIZE OF PIPE USED 6"DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____WAS LATERAL AT CURB? yesWAS ATTACHED TO MAIN yesNAME OF CONTRACTOR Malavite Etc.

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

SIGNED Doug Miller FILED AT ENGINEER'S OFFICE _____

Inspector for City

REMARKS _____

✓ *tap*
Nº 10106

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, *July 3*

RECEIVED OF *Mr. Carl Horner*

FEE OF *50*

FOR WHICH PERMISSION IS GRANTED *same*

TO TAP *San*

SEWER ON THE *West*

OF *Springfield Ave.*

AVE.

ST. TYPE OF STREET

THE PREMISES BEING LOT NO. *14355*

HOUSE NO. *1723*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *W. M. Smith, Inc.*

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**