Nº 10124

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 10-24-9/	IF SO HOW AND LOCATION FROM 169	
HOUSE NO. 1728	DISTANCE FROM FIRST MANHOLE	
SIZE OF PIPE USED	DOWN STREAM TO DITCH AT	
	CURB LINE AND DEPTH	
WAS LATERAL AT CURB?	,	
WAS ATTACHED TO MAIN 155	The Sold Edder	
WAS ATTACHED TO MAIN 155	NAME OF CONTRACTOR	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
8' DEED -	9'c Ast Inon N 30° > 9 DEEP	
SIGNED BILL CONDUS	FILED AT ENGINEER'S OFFICE	
SIGNED Inspector for City	FILED AT ENGINEER'S OFFICE	
PENABLO		

Nº 10124

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OHIO,	lada
RECEIVED OF	etrell	FEE OF \$
OR WHICH PERMISSION IS GRANTED		
O TAP	SEWER ON THE	<u>,</u>
F. S. C. T. AVE ST.	E. . TYPE OF STREET	
HE PREMISES BEING LOT NO.	, HOUSE NO,	17.58
YORK TO BE DONE IN ACCORDANCE WITH ORDINANC		
NAME OF CONTRACTOR		

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.