

N^o 10178

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 2-19-92

IF SO HOW AND LOCATION FROM
FIRST MANHOLE ~~DOWN~~ UP STREAM 3'

HOUSE NO. 517

SIZE OF PIPE USED 6" Plastic


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? NO

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR Jim Plas

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



N

SIGNED Bill Pappas

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Tap
Nº 10178

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, *July 18*

RECEIVED OF *Bliss Ewe*

FEE OF \$ *5*

FOR WHICH PERMISSION IS GRANTED *Wm*

TO TAP *San*

SEWER ON THE *5*

OF *Hamilton St*

AVE.
ST. TYPE OF STREET

THE PREMISES BEING LOT NO. *13884*

, HOUSE NO. *517*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *Bliss Ewe*

1 und
**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**