Nº 10194

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 6-9-92	IF SO HOW AND LOCATION FROM 246
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? 165	NAME OF CONTRACTOR GLOSE
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	L OF BUILDING SERVED.
$\begin{array}{c} 12' \\ \hline 17 \\ \hline \end{array}$	S'CAST INDITIONS DEEP
75° 6	2 CH21 140M
SIGNED Bill Pappar	-45° 8'6 DEFF FILED AT ENGINEER'S OFFICE
Inspector for City	

V2 10194

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

MASSILLON, OHIO, WALL 8
RECEIVED OF MICE FEE OF \$5
or which permission is granted 1.104.001
O TAP SEWER ON THE
OF 28 4))(() AVE. TYPE OF STREET
THE PREMISES BEING LOT NO. 143/17 , HOUSE NO. 648
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
NAME OF CONTRACTOR ALCICLA MALE
NAME OF CONTRACTOR 111111111111111111111111111111111111

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.