Nº 10195

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO	DISTANCE FROM FIRST MANUAL F
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	
WAS ATTACHED TO MAIN NAME OF CONTRACTORSHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.	
NEVER CAlled For Inspection!	
SIGNED BILL CAST	AAA FILED AT ENGINEER'S OFFICE
Inspector for City	
REMARKS	

Cutof

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

MASSILLON, OHIO, CHING 9
RECEIVED OF CATULAL TY-W FEE OF \$5.
DR WHICH PERMISSION IS GRANTED
SHULL SLU SEWER ON THE SHULL SLU ST. TYPE OF STREET
HE PREMISES BEING LOT NO. 3472 , HOUSE NO. 435
ORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
AME OF CONTRACTOR WILLIEL TO CO.

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.