$N^{0}$  10213

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

| DATE INSPECTED                            | IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM                     |
|---|---|
| HOUSE NO. 2420                            |   |
| SIZE OF PIPE USED                         | DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH |
| WAS LATERAL AT CURB? 755                  |   |
| WAS ATTACHED TO MAIN 45                   | NAME OF CONTRACTOR Malavitle Effec.                                       |
| SHOW BY DIAGRAM RELATION OF LATERAL TO WA | ALL OF BUILDING SERVED.   |
|   |   |
|   | 9'4"  |
| <u> </u>                                  | 1'5' AMP  |
|   |   |
|   | 8'6"DEFP  |
| SIGNED Bill Copper                        | FILED AT ENGINEER'S OFFICE  |
| //Iñspector for City                      |   |
| REMARKS                                   |   |

WTF

Nº 10213

## OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

| FERMIN TO THE SEWER   |
|---|
| MASSILLON, OHIO, July 31  |
| RECEIVED OF MACHINE EXC FEE OF \$50   |
| FOR WHICH PERMISSION IS GRANTED (XXI)   |
| TO TAP SEWER ON THE 9 OUT   |
| OF MILLON CAN MILL I) EAVE. TYPE OF STREET  |
| THE PREMISES BEING LOT NO. $14181$ , House No. $2420$   |
| WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND |
| OF THE DEPARTMENT OF PUBLIC SERVICE.  |
| NAME OF CONTRACTOR DALLWITE EXC. / White  |

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.