

Nº 10226

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 10-8-92

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 906

SIZE OF PIPE USED 6" PLASTIC


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR H&W Construction

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED. 45°



SIGNED Bill Pappas
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS SET NEW 4 IN MAIN line plastic pipe was used.

Nº 10226 *lap*

OFFICE OF THE DIRECTOR OF PUBLIC SEWERS
PERMIT TO TAP SEWER

MASSILLON, OHIO, *Oct. 7*

RECEIVED OF *H & W Contractors*

FEE OF \$ *50*

FOR WHICH PERMISSION IS GRANTED *Under*

TO TAP *Stone*

SEWER ON THE *N*

OF *Union & W. East*

AVE.

ST. TYPE OF STREET

THE PREMISES BEING LOT NO. *511, 512, 513*

HOUSE NO. *906*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *H & W Contractors*

Super America
1 unit

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**