Nº 10232

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 11-15-92	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM		
HOUSE NO			
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT  CURB LINE AND DEPTH		
WAS LATERAL AT CURB?			
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR		
SHOW BY DIAGRAM RELATION OF LATERAL TO	WALL OF BUILDING SERVED.		
v ·			
Bill	and and		
SIGNED Bull and Inspect of the Contract of the	FILED AT ENGINEER'S OFFICE		
•			

01 of f Nº 10232

## OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OHIO, C. Fair	
RECEIVED OF 11/6 LOCK	, +++	FEE OF \$
FOR WHICH PERMISSION IS GRANTED	Hueso @ 5	<u> </u>
TO TAP	WER ON THE	
OFST. T	YPE OF STREET	
THE PREMISES BEING LOT NO	CC, HOUSE NO	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE N		
OF THE DEPARTMENT OF PUBLIC SERVICE.	Statest	OHIC
NAME OF CONTRACTOR 6 6 101 110		

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.