Nº 10279

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 4-28-93	IF SO HOW AND LOCATION FROM 22 / FIRST MANHOLE DOWN STREAM 22
HOUSE NO. 4/12/	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	$A \cdot A \cdot A \cdot C \cdot A \cdot A$
WAS ATTACHED TO MAIN 155	NAME OF CONTRACTOR & spectrace Cyte.
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	L OF BUILDING SERVED.
MH 05 700 10 DEED	with Inspection T an outset 47 DEEP
25, Clea	all out set 97 DEEP
1.0	
7an/5	
SIGNED BILL GARAGE TANTE 2 DEFF Inspector for City	FILED AT ENGINEER'S OFFICE

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OHIO, AMIL 15
RECEIVED OF FIFTY Del	CARS FEE OF \$ 50
OR WHICH PERMISSION IS GRANTED DIFFE	TRA EXCAV.
D TAP SANTARY SE	WER ON THE USEST
F <i>EUTE</i> ST. TY	PE OF STREET ASHIT & BUILL
HE PREMISES BEING LOT NO. 21587	, HOUSE NO. 4/2/- ERIE FAUL
ORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO F THE DEPARTMENT OF PUBLIC SERVICE.	McDonalds
AME OF CONTRACTOR JUNETRA FYCH	14,tUnit

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.