Nº 10281

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 4-21-93	IF SO HOW AND LOCATION FROM GOES OUT BACK to FEDERAL AUE
HOUSE NO. 620	,
SIZE OF PIPE USED 6" Plastic	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	2
WAS ATTACHED TO MAIN 755	NAME OF CONTRACTOR 24 + W
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	L OF BUILDING SERVED.
	8'DERP 4+45 FEDERAL AUG
SIGNED BILL ASAM Inspector for City	FILED AT ENGINEER'S OFFICE
<i>y t</i>	

top

Nº 10281

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

MASSILLON, OHIO,	9
RECEIVED OF ALL CONTROL ON CALLED	FEE OF S
or which permission is granted 140/(2))(
O TAP MON SEWER ON THE	* .
THE PREMISES BEING LOT NO. $486 + 9487$, House No. 62	
HE PREMISES BEING LOT NO. $486 + 487$, House No. 62	20
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CIT	
IAME OF CONTRACTOR AUTO	ct
Note: This permit covers work outside of building only.	

walls of building is subject to Massillon Board of Health Regulations.