Nº 10286

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

| DATE INSPECTED 6-7-93 | IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM 154 | |
|---|--|--|
| HOUSE NO3/29 | | |
| SIZE OF PIPE USED | DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT | |
| WAS LATERAL AT CURB? 465 | CURB LINE AND DEPTH | |
| WAS ATTACHED TO MAIN 155 | NAME OF CONTRACTOR TiSSO EME. | |
| SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED. | | |
| | 5'ps & 32° | |
| SIGNED BW Canal Inspector for C | 122° / DEFE Sity FILED AT ENGINEER'S OFFICE SITY | |
| REMARKS | | |

OFFICE OF THE DIRECTOR OF PUBLIC SEI

| T 4 | 10200 |
|-----|-------|
| | tap |

10286

 N^0

PERMIT TO TAP SEWER

| 701 | MASSILLON, OHIO, MAY 20H |
|--|--|
| RECEIVED OF K& M BUILT | ERS FEE OF \$ |
| FOR WHICH PERMISSION IS GRANTED | TEX |
| TO TAP CONITAL SE | WER ON THE SOUTH |
| OF COSTO LIGHT CIR MY ST. TO | YPE OF STREET |
| THE PREMISES BEING LOT NO. 14763 | , HOUSE NO. 3129 |
| WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE N | 10. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND |
| OF THE DEPARTMENT OF PUBLIC SERVICE. | Mr + Mrs JOHN KENNE |
| NAME OF CONTRACTOR TISSOT | |

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.