

Nº 10319

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 7-30-93

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 1809

SIZE OF PIPE USED 6" to 4"

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? back of lot


WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR Malavite

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



8 1/2' deep @ tie in
33' SE corner of lot to tie in
29' from back lot line to unit
23' from back lot line to 22 1/2° bends
17' East lot line to 22 1/2° bends
10' East lot line to side of unit



@ tie in 4' clay
to 6" furnace
5' piece of 6" p
45° then 10' to
45° then 23' p
22 1/2° to 1' piece
to 1' piece to 22
piece then 6" p
then 10' piece 4'

SIGNED Douglas A. Miller
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS lateral goes from back of lot on Woodbine; then travels SE to Ledgerwood Blvd. to 90° w/ 5' piece straight up; cap

tap
Nº 10319

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, July 26

RECEIVED OF Don Duvall

FEE OF \$ 50

FOR WHICH PERMISSION IS GRANTED same

TO TAP same

SEWER ON THE 5

OF Woodbine

AVE.

ST. TYPE OF STREET

THE PREMISES BEING LOT NO. 14403

, HOUSE NO. 1809

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Malarite
Epe

Duvall
1 unit
**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**