Nº 10325

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

| DATE INSPECTED 9-3-9-3 | IF SO HOW AND LOCATION FROM FIRST MANHOLE DESCRIPTION STREAM | |
|---|---|--|
| HOUSE NO. /306 | 90 | |
| SIZE OF PIPE USED | DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH | |
| WAS LATERAL AT CURB? | | |
| WAS ATTACHED TO MAIN 755 | NAME OF CONTRACTOR Timot Effe. | |
| SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED. | | |
| | Set Y and sand trap | |
| SIGNED Bill Panas Appector for City | FILED AT ENGINEER'S OFFICE | |
| DEMARKS | $\mathcal{L}_{\mathbf{v}}^{v}$ | |

№ 10325 /

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

| | MASSILLON, OHIO, | <u> [] [] [] [] [] [] [] [] [] [] [] [] [] </u> |
|--------------------------------------|--------------------------|---|
| RECEIVED OF | Shout Epo | FEE OF \$ |
| OR WHICH PERMISSION IS GRANTED | <u> </u> | · |
| O TAP | SEWER ON THE | <u></u> |
| of Condo A | AVE. | |
| THE PREMISES BEING LOT NO. 4// | 10 44/9/, HOUSE | NO. 1360 |
| YORK TO BE DONE IN ACCORDANCE WITH | Section 29 of DULY PAS | SED BY THE CITY COUNCIL, AND |
| OF THE DEPARTMENT OF PUBLIC SERVICE. | , autuce | Hurld Poun |
| NAME OF CONTRACTOR 1 | ers work outside of bui | - / unix |
| Note: This nermit cave | ers work outside of buil | lding only. Any work |

walls of building is subject to Massillon Board of Health Regulations.