

N^o 10382

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED 5-17-94

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 11'

HOUSE NO. 2827

SIZE OF PIPE USED 6"


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? YES

WAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR A. Glick

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



SIGNED Bill Pason Inspector for City FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº 10382

OFFICE OF THE DIRECTOR OF PUBLIC SEI
PERMIT TO TAP SEWER

MASSILLON, OHIO, May 13th

RECEIVED OF

(Robert Barton) Jacob Glick

FEE OF \$

51

FOR WHICH PERMISSION IS GRANTED

TO TAP

Sanitary

SEWER ON THE

300th

OF

Lee Ave N.W.

AVE.

ST. TYPE OF STREET

THE PREMISES BEING LOT NO.

14320

HOUSE NO.

2827

WORK TO BE DONE IN ACCORDANCE WITH C
OF THE DEPARTMENT OF PUBLIC SERVICE.

Section 29
Codified Ordinances

DULY PASSED BY THE CITY COUNCIL, AND

Robt Barton

NAME OF CONTRACTOR

Glick

1 unit

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**